


TEST METER

Quartz Precision Thermo-Hydrograph





Model	3-3122
Temperature Measuring Range	~ 15 ~ 40°C
Humidity Measuring	0 - 100% (step 1°C)
Size (W X D X H)	361 X 150 X 287 mm
Days	1 Day, 7 Days

Model	3-3127
Temperature Measuring Range	~ 20 ~ 50°C (1°C)
Humidity Measuring	0 - 100% (1%)
Size (W X D X H)	361 X 150 X 287 mm
Days	1 Day, 7 Days, 31 Days

Thermo-Hygrometer

7542

Jumbo



Model	Measuring Range	Accuracy	Dimension (mm)
7542	20 ~ 100% 0 ~ 50°C	±4%, 1°C	Φ135 x 33 (D)
Jumbo	10 ~ 99% -10 ~ 60°C	±5%, 1°C	107 x 99 x 20

Refractometer



Model	Measuring Range	Minimum Indication	Dimension (mm)	Weight (g)
N-1	Brix 0.0~32.0%	Brix 0.2%	40 x 40 x 180	170
N-50E	Brix 0.0~50.0%	Brix 0.5%	40 x 40 x 140	140

NON-Contact Thermometer



Model	Measuring Range	Dimension W x H x D (mm)	Weight (g)
CT-2000	-20°C ~ 420°C	40 x 170 x 44	200
PM-131A	-32°C ~ 545°C	135 x 195 x 40	320
PM-132A	-32°C ~ 600°C	135 x 195 x 40	320
PM-133A	-32°C ~ 760°C	135 x 195 x 40	320